### भारत पेट्रोलियम कॉर्पोरेशन लिमिटेड

भारत सरकार का उपक्रम कोच्चि रिफ़ाइनरी



KR.HSE.ENV.05.HSSE.HECCR/02/2022/ EC No.J-11011/78/96-IA-II 15.12.2022

To

The Additional Principal Chief conservator of Forests (C) Ministry of Environment, Forest & Climate Change 4<sup>th</sup> Floor, E&F Wings, Kendriya sadan, Koramangala Bangalore-560 034

Dear Sir,

Sub: Submission of Half yearly compliance report on Environmental Clearance issued by the Ministry of Environment, Forests and Climate Change (MoEF & CC)

Ref: EC No.J-11011/78/96-IA-II dated. 05.03.1997 issued for the Project "Installation of Diesel Hydro De-Sulphurisation (DHDS) project M/s Bharat Petroleum Corporation Ltd - Kochi Refinery (Formerly Cochin Refineries Ltd)".

Please find enclosed the compliance reports on the various conditions laid down by MoEF &CC, pertaining to the half year period from 1<sup>st</sup> April 2022 to 30<sup>th</sup> September 2022 for the said project. Thanking you,

Very truly yours

For BPCL Kochi Refinery

Ramachandran, M.K

General Manager in Charge (HSE)

Encl: 1.Six Monthly Compliance Report

Cc:

1. The Member Secretary
Central Pollution Control Board
Parivesh Bhawan
East Arjun Nagar
Delhi - 110 032

The Member Secretary
 Kerala State Pollution Control Board
 Plamoodu Junction
 Pattom Palace
 Thiruvananthapuram - 695 004

पोस्ट बैग नं: 2, अम्बलमुगल - 682 302, एरणाकुलम ज़िला, केरल, दूरभाषः 0484 - 2722061 - 69 फैक्सः 0484 - 2720961 / 2721094 पंजीकृत कार्यालयः भारत भवन, 4 & 6, क्रीमभाय रोड, बेलार्ड इस्टेट, पी. बी. नं. 688 मुंबई -400 001 Compliance Status of Environmental Clearance conditions for installation of Diesel Hydro Desulphurisation (DHDS) project accorded by J-11011/78/96-IA-II dated 05.03.1997

Status of the project: Project commissioned in 2000

| ITEM NO. | ITEM DESCRIPTION   | Status as on 30.09.2022  |
|----------|--|--|
| 1        | All conditions stipulated by MoEF & CC while according approval for Capacity Expansion Project   | Complied   |
| 2        | No expansion or modernization of the Plant should be carried out without approval of the MoEF & CC   | Complied.  |
| 3        | The project authority must strictly adhere to the stipulations laid down by the Kerala State Pollution Control Board and the State Govt.   | Complied   |
| 4        | The total SO <sub>2</sub> emission from BPCL Kochi Refinery including DHDS Project should not exceed the norm of 1607 Kg./hr. (Refer MoEF& CC vide letter No.J-110/1/78/96.IA.II dated 9 <sup>th</sup> February,1999)  | Complied; It has been reduced to 1579 kg/hr. as per latest EC for MS block project.  |
| 5        | The existing ETP should be adequately augmented or additional treatment facilities should be provided to accommodate the additional effluent load from DHDS project before commissioning the project to ensure that the treated effluent meets the MINAS standard. | New ETP has been commissioned along with the DHDS Project and New ETP with higher capacity also erected as part of IREP (Integrated Refinery Expansion Project).   |
| 6        | Time bound action plan for disposal of oil sludge / recovery of oil and design details of the solid waste disposal pit should be furnished to the Ministry within a period of 3 months.  | Complied. A scheme for the recovery of oil from accumulated sludge has been implemented. All the accumulated sludge at that point of time was processed and currently there is no accumulated stock of oily sludge. Sludge is being processed in Delayed Coker Unit, which has been commissioned as part of IREP |

|   |   | project.  A secured landfill facility for storing hazardous wastes was commissioned in March, 2005 and also we have rate contract with KEIL (Kerala Enviro Infrastructure limited), a PCB approved installation for the Hazardous waste disposal in Kerala. |
|---|---|---|
| 7 | SRU having an efficiency of more than 99% should be installed.  | Complied.  Additional Sulphur Recovery units with newer technology and higher efficiency of 99.9% have been commissioned as part of later projects viz. CEMP - II and IREP.   |
| 8 | The ground water quality should be monitored and the report should be submitted to the Ministry every six months. | Complied. Ground water quality report attached as <b>Annexure I</b> .   |

Annexure - 1

|        |          |                | DATA ON STA        | ACK EMIS | SIONS FRO            | OM BPCL                 | KOCHI REF               | INERY (Old             | Refinery i | ncluding CE | MP - II)   |                    |                       | FILE. |
|--------|----------|----------------|--------------------|----------|----------------------|-------------------------|-------------------------|------------------------|------------|-------------|------------|--------------------|-----------------------|-------|
|        |          |                |                    |          | PERIOD -             | 1 <sup>st</sup> April 2 | 022 to 30 <sup>th</sup> | Septembe               | er 2022    |             |            | THE REAL PROPERTY. |                       | HI V  |
| Sl.no. | STACK /  | No. of samples | Permitted emission | Par      | ticulate m<br>mg/Nm3 |                         | Sulphu                  | Sulphur dioxide mg/Nm3 |            | Emiss       | ion rate N | lm3/hr.            | Percentage compliance |       |
|        | UNIT     | analysed       | Nm3/hr.            | min      | max                  | Avg.                    | min                     | max                    | avg        | min         | max        | avg                | SPCB                  | MoEF  |
| 1      | KH 1 B   | 4              | 45000              | 7.3      | 64.21                | 36.55                   | 22.30                   | 360.83                 | 191.23     | 22953       | 35250      | 28424.5            | 100                   | 100   |
| 2      | NH2/HH1  | 3              | 102000             | 8.2      | 72.19                | 49.07                   | 226.28                  | 234.31                 | 230.30     | 48438       | 72221      | 57888.0            | 100                   | 100   |
| 3      | FH1      | 4              | 25000              | 6.5      | 37.25                | 21.04                   | 204.42                  | 212.27                 | 208.35     | 22719       | 24235      | 23728.0            | 100                   | 100   |
| 4      | FH3/COB  | 4              | 150000             | 9.4      | 60.28                | 37.41                   | 49.70                   | 141.70                 | 108.82     | 83261       | 99308      | 90688.8            | 100                   | 100   |
| 5      | UB10     | 4              | 136000             | 22.7     | 63.82                | 42.09                   | 598.31                  | 822.00                 | 727.83     | 21825       | 92643      | 45984.8            | 100                   | 100   |
| 6      | UB9      | 4              | 70000              | 20.5     | 67.23                | 45.42                   | 521.37                  | 823.66                 | 672.52     | 28870       | 61493      | 40328.3            | 100                   | 100   |
| 7      | DSX 002  | 4              | 35000              | 19.4     | 63.84                | 43.75                   | 293.20                  | 841.93                 | 587.49     | 25171       | 29613      | 27934.5            | 100                   | 100   |
| 8      | DDHI     | 4              | 27000              | 17.6     | 40.41                | 30.31                   | 345.50                  | 688.02                 | 572.31     | 23336       | 26447      | 25260.3            | 100                   | 100   |
| 9      | CH21     | 4              | 130000             | 9.2      | 30.27                | 18.63                   | 180.60                  | 375.96                 | 278.48     | 11478       | 100688     | 73204.3            | 100                   | 100   |
| 10     | CH22     | 4              | 35000              | 7.9      | 71.34                | 37.60                   | 103.60                  | 312.55                 | 203.18     | 25924       | 34017      | 30115.8            | 100                   | 100   |
| 11     | UB7      | 2              | 150000             | 23.6     | 46.95                | 35.28                   | 5.20                    | 195.36                 | 100.28     | 111963      | 113958     | 112960.5           | 100                   | 100   |
| 12     | CPP/HRSG | 2              | 277900             | 23.2     | 47.38                | 35.29                   | 44.50                   | 263.99                 | 154.25     | 151717      | 161184     | 156450.5           | 100                   | 100   |
| 13     | BITUROX  | 3              | 23000              | 12.3     | 30.24                | 21.85                   | 44.50                   | 271.08                 | 190.04     | 14174       | 18726      | 15804.3            | 100                   | 100   |
| 14     | CH 223   | 4              | 51000              | 6.2      | 35.86                | 19.68                   | 125.80                  | 357.79                 | 240.64     | 46378       | 68555      | 53869.8            | 100                   | 100   |
| 15     | GT2 HRSG | 3              | 427000             | 20.4     | 45.88                | 33.69                   | 7.80                    | 74.17                  | 31.69      | 122021      | 254712     | 176200.0           | 100                   | 100   |
| 16     | UB 11    | 4              | 158000             | 23.84    | 33.20                | 27.10                   | 586.00                  | 813.94                 | 693.70     | 68787       | 110376     | 85715.3            | 100                   | 100   |
| 17     | NHTCCR   | 2              | 118000             | 15.4     | 59.82                | 37.61                   | 2.61                    | 232.00                 | 117.31     | 104483      | 119375     | 111929.0           | 100                   | 100   |
| 18     | VHH 02   | 3              | 72000              | 20.82    | 28.32                | 24.25                   | 310.33                  | 327.35                 | 318.84     | 48356       | 70327      | 56972.0            | 100                   | 100   |
| 19     | DSX-301  | 4              | 22000              | 24.8     | 58.17                | 43.15                   | 83.80                   | 1127.35                | 691.46     | 12668       | 14310      | 13784.3            | 100                   | 100   |
| 20     | UB8      | 4              | 70000              | 31.4     | 70.34                | 53.30                   | 416.20                  | 890.61                 | 689.18     | 29524       | 52588      | 39999.8            | 100                   | 100   |



# BHARAT PETROLEUM CORPORATION LIMITED KOCHI REFINERY

### HSE DEPARTMENT

KR.HSE.SAFE.05.SLMR.SKP

02.07.2022

Sub: Noise level at Boundary Wall.

Noise level at various locations near the boundary wall inside the refinery was measured on 02.07.2022 at **NIGHT TIME**. The observed values are given below.

| Sl. No. | Location  | Sound<br>level | Remarks          |
|---------|---|----------------|------------------|
| 1.      | South of tankYT-30 (Near to Parking)                      | 56             | -                |
| 2.      | Near T T gate (PDPP gate)                                 | 61             |                  |
| 3.      | South of Project warehouse                                | 59             | -                |
| 4.      | 220 KV line crossing near rain water harvesting pond      | 52             | -                |
| 5.      | DHDS Tower No- 1  | 55             |                  |
| 6.      | Rear side of DHDS fire station                            | 53             |                  |
| 7.      | Near Chalikkara gate                                      | 56             | -                |
| 8.      | Near TK-25  |                | 3                |
| 9.      | East of MS Block  |                | -                |
| 10.     | South of DHDS Flare                                       | 59             | -                |
| 11.     | Near NHT-CCR-AAQMS (Near MSBP boundary)                   | 60             |                  |
| 12.     | West of tank YT-902(DHDS)                                 | 53             | -                |
| 13.     | Rear side of PIBU office(opp. IPTC)                       | 50             | -                |
| 14.     | Bottling plant entrance from refinery(IPTC Road)          | 59             | •                |
| 15.     | North of LNG skid (GT-2 Road end)                         | 61             | V=               |
| 16.     | Near IREP gate  | 60             | -                |
| 17.     | DCU   | 63             | -                |
| 18.     | South of UB-12  | 63             | -                |
| 19.     | North of VGO labour amenity building                      | 58             |                  |
| 20.     | Behind IREP site office                                   | 60             |                  |
| 21.     | Below Coke Conveyor area near railway gate(PWC 4)-offline | 49             | Conveyor Offline |
| 22.     | Below Coke Conveyor area near railway gate- RLS-1         | 45             | Conveyor Offline |
| 23.     | Below Coke Conveyor area near outlet A -RLS-2             | 47             | Conveyor Offline |
| 24.     | Drum Plant gate   | 56             | -                |

Ta

(r)

M (HSE) I/C

Smit Kumar Pal Manager (Safety)



#### BHARAT PETROLEUM CORPORATION LIMITED **KOCHI REFINERY**

#### HSE DEPARTMENT

KR.HSE.SAFE.05.SLMR.SKP

21.09.2022

Sub: Noise level at Boundary Wall.

Noise level at various locations near the boundary wall inside the refinery was measured on 21.09.2022 at day time. The observed values are given below.

| Sl. No. | Location  | Sound<br>level | Remarks          |
|---------|---|----------------|------------------|
| 1.      | South of tank YT-30 (Near to Parking)                     | 62             |                  |
| 2.      | Near T T gate (PDPP gate)                                 | 63             |                  |
| 3.      | South of Project warehouse                                | 59             | -                |
| 4.      | 220 KV line crossing near rain water harvesting pond      | 57             | -                |
| 5.      | DHDS Tower No- 1  | 56             |                  |
| 6.      | Rear side of DHDS fire station                            | 59             | -                |
| 7.      | Near Chalikkara gate                                      | 61             | -                |
| 8.      | Near TK-25  |                |                  |
| 9.      | East of MS Block  |                | -                |
| 10.     | South of DHDS Flare                                       | 60             | -                |
| 11.     | Near NHT-CCR-AAQMS (Near MSBP boundary)                   | 61             |                  |
| 12.     | West of tank YT-902(DHDS)                                 | 50             | -                |
| 13.     | Rear side of PIBU office(opp. IPTC)                       | 57             | -                |
| 14.     | Bottling plant entrance from refinery(IPTC Road)          | 61             | -                |
| 15.     | North of LNG skid (GT-2 Road end)                         | 64             | -                |
| 16.     | Near IREP gate  | 61             | -                |
| 17.     | DCU   | 63             | -                |
| 18.     | South of UB-12  | 60             | -                |
| 19.     | North of VGO labour amenity building                      | 62             | -                |
| 20.     | Behind IREP site office                                   | 61             | •                |
| 21.     | Below Coke Conveyor area near railway gate(PWC 4)-offline | 60             | Conveyor Offline |
| 22.     | Below Coke Conveyor area near railway gate- RLS-1         | 63             | Conveyor Offline |
| 23.     | Below Coke Conveyor area near outlet A -RLS-2             | 64             | Conveyor Offline |
| 24.     | Drum Plant gate   | 60             |                  |

To: DGM (F&S)

(r)

GM (HSE) 1/C

Smit Kumar Pal Manager (Safety)



### **BOREWELL WATER TEST REPORT**

Bore well No. 70

Date of Sample: 12.4.2022 Date of Testing: 20.4.2022

KR.TECH.QC.26.DRINK.WATR

| SI<br>No: | Test Parameters    | Unit | Method           | Result             | Acceptable limi |
|-----------|--------------------|------|------------------|--------------------|-----------------|
| 5         | рН                 |      | IS 3025 (P:11)   | 7.6                | 6.5 - 8.5       |
| 15        | Oil                | mg/L | IS 3025 (P:39)   | nîl                | nil             |
|           | Metals             |      |                  |                    |                 |
| 16        | Silver (as Ag)     | mg/L | IS13428 Annexe J | BDL<br>(MDL=0.005) | 0.1 (Max)       |
| 17        | Aluminium (as Al)  | mg/L | IS 3025 (P:55)   | BDL(MDL=0.002)     | 0.03 (Max)      |
| 18        | Boron (as B)       | mg/L | IS 3025 (P:57)   | BDL(MDL=0.01)      | 0.5 (Max)       |
| 19        | Barium (as Ba)     | mg/L | IS13428 Annexe F | BDL(MDL=0.01)      | 0.7 (Max)       |
| 20        | Calcium (as Ca)    | mg/L | IS 3025 (P:40)   | 23                 | 75 (Max)        |
| 21        | Cadmium (as Cd)    | mg/L | IS 3025 (P:41)   | BDL(MDL=0.001)     | 0.003 (Max)     |
| 22        | Chromium (as Cr)   | mg/L | IS 3025 (P:52)   | BDL(MDL=0.01)      | 0.05 (Max)      |
| 23        | Copper (as Cu)     | mg/L | IS 3025 (P:42)   | BDL(MDL=0.01)      | 0.05 (Max)      |
| 24        | Iron (as Fe)       | mg/L | IS 3025 (P:53)   | 0.09               | 0.3 (Max)       |
| 25        | Magnesium (as Mg)  | mg/L | IS 3025 (P:46)   | 4                  | 30 (Max)        |
| 26        | Manganese (as Mn)  | mg/L | IS 3025 (P:59)   | BDL(MDL=0.01)      | 0.1 (Max)       |
| 27        | Nickel (as Ni)     | mg/L | IS 3025 (P:54)   | BDL(MDL=0.01)      | 0.02 (Max)      |
| 28        | Molybdenum (as Mo) | mg/L | IS 3025 (P:02)   | BDL(MDL=0.002      | 0.07 (Max)      |
| 29        | Lead (as Pb)       | mg/L | IS 3025 (P:47)   | BDL(MDL=0.01)      | 0.01 (Max)      |
| 30        | Zinc (as Zn)       | mg/L | IS 3025 (P:49)   | 0.2                | 5 (Max)         |
| 31        | Arsenic (as As)    | mg/L | IS 3025 (P:37)   | BDL(MDL0.005)      | 0.01 (Max)      |
| 32        | Mercury (as Hg)    | mg/L | IS 3025 (P:48)   | BDL(MDL0.0001)     | 0.001(Max)      |
| 33        | Selenium (as Se)   | mg/L | IS 3025 (P:56)   | BDL(MDL=0.001)     | 0.1 (Max)       |
| 34        | Antimony (as Sb)   | mg/L | APHA:3113B       | BDL(MDL=0.001)     | Max0.1          |

BDL: Below Detection Limit MDL: Minimum Detection Limit



## BOREWELL WATER TEST REPORT

Bore well No. 43

Date of Sample: 20.5.2022 Date of Testing: 27.5.2022

| SI 7.5.2022 |                    | KR.TECH.QC.26.DRINK.WATR |                  |                    |                |  |
|-------------|--------------------|--------------------------|------------------|--------------------|----------------|--|
| No:         | Test Parameters    | Unit                     | Method           | Result             | Acceptable lim |  |
| 5           | рН                 |                          | IS 3025 (P:11)   | 7.9                | 6.5 - 8.5      |  |
| 15          | Oil                | mg/L                     | IS 3025 (P:39)   | nil                | nil            |  |
|             | Metals             |                          |                  |                    |                |  |
| 16          | Silver (as Ag)     | mg/L                     | IS13428 Annexe J | BDL<br>(MDL=0.005) | 0.1 (Max)      |  |
| 17          | Aluminium (as Al)  | mg/L                     | IS 3025 (P:55)   | BDL(MDL=0.002)     | 0.03 (Max)     |  |
| 18          | Boron (as B)       | mg/L                     | IS 3025 (P:57)   | BDL(MDL=0.01)      | 0.5 (Max)      |  |
| 19          | Barium (as Ba)     | mg/L                     | IS13428 Annexe F | BDL(MDL=0.01)      | 0.7 (Max)      |  |
| 20          | Calcium (as Ca)    | mg/L                     | IS 3025 (P:40)   | 18                 | 75 (Max)       |  |
| 21          | Cadmium (as Cd)    | mg/L                     | IS 3025 (P:41)   | BDL(MDL=0.001)     | 0.003 (Max)    |  |
| 22          | Chromium (as Cr)   | mg/L                     | IS 3025 (P:52)   | BDL(MDL=0.01)      | 0.05 (Max)     |  |
| 23          | Copper (as Cu)     | mg/L                     | IS 3025 (P:42)   | BDL(MDL=0.01)      | 0.05 (Max)     |  |
| 24          | Iron (as Fe)       | mg/L                     | IS 3025 (P:53)   | 0.06               | 0.3 (Max)      |  |
| 25          | Magnesium (as Mg)  | mg/L                     | IS 3025 (P:46)   | 5                  | 30 (Max)       |  |
| 26          | Manganese (as Mn)  | mg/L                     | IS 3025 (P:59)   | BDL(MDL=0.01)      | 0.1 (Max)      |  |
| 27          | Nickel (as Ni)     | mg/L                     | IS 3025 (P:54)   | BDL(MDL=0.01)      | 0.02 (Max)     |  |
| 28          | Molybdenum (as Mo) | mg/L                     |                  | BDL(MDL=0.002      | 0.07 (Max)     |  |
| 29          | Lead (as Pb)       | mg/L                     |                  | BDL(MDL=0.01)      | 0.01 (Max)     |  |
| 30          | Zinc (as Zn)       | mg/L                     |                  | 0.1                | 5 (Max)        |  |
| 31          | Arsenic (as As)    | mg/L                     | IS 3025 (P:37)   | BDL(MDL0.005)      | 0.01 (Max)     |  |
| 32          | Mercury (as Hg)    | mg/L                     |                  | BDL(MDL0.0001)     | 0.001(Max)     |  |
| 33          | Selenium (as Se)   | mg/L                     |                  | BDL(MDL=0.001)     | 0.1 (Max)      |  |
| 34          | Antimony (as Sb)   | mg/L                     |                  | BDL(MDL=0.001)     | Max0.1         |  |

MDL: Minimum Detection Limit



## BOREWELL WATER TEST REPORT

Bore well No. 57

Date of Sample: 11.6.2022 Date of Testing: 22.6.2022

| SI<br>No: | Test Parameters                        | Unit  | Method           | Result             | Acceptable lim      |
|-----------|--|-------|------------------|--------------------|---------------------|
| 5         | рН                                     |       | IS 3025 (P:11)   | 7.5                |                     |
| 15        | Oil                                    | mg/L  | IS 3025 (P:39)   |                    | 6.5 – 8.5           |
|           | Metals                                 | 18/ - | 13 3023 (F.33)   | nil                | nil                 |
| 16        | Silver (as Ag)                         | mg/L  | IS13428 Annexe J | BDL<br>(MDL=0.005) | 0.1 (Max)           |
| 17        | Aluminium (as Al)                      | mg/L  | IS 3025 (P:55)   | BDL(MDL=0.002)     | 0.03 (Max)          |
| 18        | Boron (as B)                           | rng/L | IS 3025 (P:57)   | BDL(MDL=0.01)      | 0.5 (Max)           |
| 19        | Barium (as Ba)                         | mg/L  | IS13428 Annexe F |                    | 0.7 (Max)           |
| 20        | Calcium (as Ca)                        | mg/L  | IS 3025 (P:40)   | 17                 | 75 (Max)            |
| 21        | Cadmium (as Cd)                        | rng/L | IS 3025 (P:41)   | BDL(MDL=0.001)     | 0.003 (Max)         |
| 22        | Chromium (as Cr)                       | mg/L  | IS 3025 (P:52)   | BDL(MDL=0.01)      | 0.05 (Max)          |
| 23        | Copper (as Cu)                         | mg/L  | IS 3025 (P:42)   | BDL(MDL=0.01)      | 0.05 (Max)          |
| 24        | Iron (as Fe)                           | mg/L  | IS 3025 (P:53)   | 0.08               | 0.3 (Max)           |
| 25        | Magnesium (as Mg)                      | mg/L  | IS 3025 (P:46)   | 7                  | 30 (Max)            |
| 26        | Manganese (as Mn)                      | mg/L  | IS 3025 (P:59)   | BDL(MDL=0.01)      | 0.1 (Max)           |
| 27        | Nickel (as Ni)                         | mg/L  | IS 3025 (P:54)   | BDL(MDL=0.01)      | 0.02 (Max)          |
| 28        | Molybdenum (as Mo)                     | mg/L  | IS 3025 (P:02)   | BDL(MDL=0.002      | 0.07 (Max)          |
| 29        | Lead (as Pb)                           | mg/L  | IS 3025 (P:47)   | BDL(MDL=0.01)      | 0.01 (Max)          |
| 30        | Zinc (as Zn)                           | mg/L  | IS 3025 (P:49)   | 0.1                | 5 (Max)             |
| 31        | Arsenic (as As)                        | mg/L  |                  | BDL(MDL0.005)      | 0.01 (Max)          |
| 32        | Mercury (as Hg)                        | mg/L  |                  | BDL(MDL0.0001)     | 0.001 (Max)         |
| 33        | Selenium (as Se)                       | mg/L  |                  | BDL(MDL=0.001)     |                     |
| 34        | Antimony (as Sb) Below Detection Limit | mg/L  |                  | BDL(MDL=0.001)     | 0.1 (Max)<br>Max0.1 |

BDL: Below Detection Limit MDL: Minimum Detection Limit

> S. Fa John S.Mahamed Iqbal Manager (Quality Control)



### BOREWELL WATER TEST REPORT

Bore well No. 7

Date of Sample: 30.7.2022

KR.TECH.QC.26.DRINK.WATR

| SI<br>No: | Test Parameters    | Unit | Method           | Result             | Acceptable lim |  |
|-----------|--------------------|------|------------------|--------------------|----------------|--|
| 5         | рН                 |      | IS 3025 (P:11)   | 7.8                | 6.5 - 8.5      |  |
| 15        | Oil                | mg/L | IS 3025 (P:39)   | nil                | nil            |  |
|           | Metals             |      |                  |                    |                |  |
| 16        | Silver (as Ag)     | mg/L | IS13428 Annexe J | BDL<br>(MDL=0.005) | 0.1 (Max)      |  |
| 17        | Aluminium (as Al)  | mg/L | IS 3025 (P:55)   | BDL(MDL=0.002)     | 0.03 (Max)     |  |
| 18        | Boron (as B)       | mg/L | IS 3025 (P:57)   | BDL(MDL=0.01)      | 0.5 (Max)      |  |
| 19        | Barium (as Ba)     | mg/L | IS13428 Annexe F | BDL(MDL=0.01)      | 0.7 (Max)      |  |
| 20        | Calcium (as Ca)    | mg/L | IS 3025 (P:40)   | 14                 | 75 (Max)       |  |
| 21        | Cadmium (as Cd)    | mg/L | IS 3025 (P:41)   | BDL(MDL=0.001)     | 0.003 (Max)    |  |
| 22        | Chromium (as Cr)   | mg/L | IS 3025 (P:52)   | BDL(MDL=0.01)      | 0.05 (Max)     |  |
| 23        | Copper (as Cu)     | mg/L | IS 3025 (P:42)   | BDL(MDL=0.01)      | 0.05 (Max)     |  |
| 24        | Iron (as Fe)       | mg/L | IS 3025 (P:53)   | 0.08               | 0.3 (Max)      |  |
| 25        | Magnesium (as Mg)  | mg/L | IS 3025 (P:46)   | 5                  | 30 (Max)       |  |
| 26        | Manganese (as Mn)  | mg/L | IS 3025 (P:59)   | BDL(MDL=0.01)      | 0.1 (Max)      |  |
| 27        | Nickel (as Ni)     | mg/L | IS 3025 (P:54)   | BDL(MDL=0.01)      | 0.02 (Max)     |  |
| 28        | Molybdenum (as Mo) | mg/L | IS 3025 (P:02)   | BDL(MDL=0.002      | 0.07 (Max)     |  |
| 29        | Lead (as Pb)       | mg/L | IS 3025 (P:47)   | BDL(MDL=0.01)      | 0.01 (Max)     |  |
| 30        | Zinc (as Zn)       | mg/L | IS 3025 (P:49)   | 0.1                | 5 (Max)        |  |
| 31        | Arsenic (as As)    | mg/L | IS 3025 (P:37)   | BDL(MDL0.005)      | 0.01 (Max)     |  |
| 32        | Mercury (as Hg)    | mg/L | IS 3025 (P:48)   | BDL(MDL0.0001)     | 0.001(Max)     |  |
| 33        | Selenium (as Se)   | mg/L | IS 3025 (P:56)   | BDL(MDL=0.001)     | 0.1 (Max)      |  |
| 34        | Antimony (as Sb)   | mg/L | APHA:3113B       | BDL(MDL=0.001)     | Max0.1         |  |

BDL: Below Detection Limit MDL: Minimum Detection Limit



### BOREWELL WATER TEST REPORT

Bore well No. 24

Date of Sample: 19.8.2022 Date of Testing: 26.8.2022

KR.TECH.QC.26.DRINK.WATR

| SI<br>No: | Test Parameters    | Unit | Method           | Result             | Acceptable lim |
|-----------|--------------------|------|------------------|--------------------|----------------|
| 5         | рН                 | *    | IS 3025 (P:11)   | 7.3                | 6.5 - 8.5      |
| 15        | Oil                | mg/L | IS 3025 (P:39)   | nil                | nil            |
|           | Metals             |      |                  |                    |                |
| 16        | Silver (as Ag)     | mg/L | IS13428 Annexe J | BDL<br>(MDL=0.005) | 0.1 (Max)      |
| 17        | Aluminium (as Al)  | mg/L | IS 3025 (P:55)   | BDL(MDL=0.002)     | 0.03 (Max)     |
| 18        | Boron (as B)       | mg/L | IS 3025 (P:57)   | BDL(MDL=0.01)      | 0.5 (Max)      |
| 19        | Barium (as Ba)     | mg/L | IS13428 Annexe F | BDL(MDL=0.01)      | 0.7 (Max)      |
| 20        | Calcium (as Ca)    | mg/L | IS 3025 (P:40)   | 12                 | 75 (Max)       |
| 21        | Cadmium (as Cd)    | mg/L | IS 3025 (P:41)   | BDL(MDL=0.001)     | 0.003 (Max)    |
| 22        | Chromium (as Cr)   | mg/L | IS 3025 (P:52)   | BDL(MDL=0.01)      | 0.05 (Max)     |
| 23        | Copper (as Cu)     | mg/L | IS 3025 (P:42)   | BDL(MDL=0.01)      | 0.05 (Max)     |
| 24        | Iron (as Fe)       | mg/L | IS 3025 (P:53)   | 0.08               | 0.3 (Max)      |
| 25        | Magnesium (as Mg)  | mg/L | IS 3025 (P:46)   | 4                  | 30 (Max)       |
| 26        | Manganese (as Mn)  | mg/L | IS 3025 (P:59)   | BDL(MDL=0.01)      | 0.1 (Max)      |
| 27        | Nickel (as Ni)     | mg/L | IS 3025 (P:54)   | BDL(MDL=0.01)      | 0.02 (Max)     |
| 28        | Molybdenum (as Mo) | mg/L | IS 3025 (P:02)   | BDL(MDL=0.002      | 0.07 (Max)     |
| 29        | Lead (as Pb)       | mg/L | IS 3025 (P:47)   | BDL(MDL=0.01)      | 0.01 (Max)     |
| 30        | Zinc (as Zn)       | mg/L | IS 3025 (P:49)   | 0.1                | 5 (Max)        |
| 31        | Arsenic (as As)    | mg/L | IS 3025 (P:37)   | BDL(MDL0.005)      | 0.01 (Max)     |
| 32        | Mercury (as Hg)    | mg/L | IS 3025 (P:48)   | BDL(MDL0.0001)     | 0.001(Max)     |
| 33        | Selenium (as Se)   | mg/L | IS 3025 (P:56)   | BDL(MDL=0.001)     | 0.1 (Max)      |
| 34        | Antimony (as Sb)   | mg/L | APHA:3113B       | BDL(MDL=0.001)     | Max0.1         |

BDL: Below Detection Limit MDL: Minimum Detection Limit